


Well Construction Details and Log of Boring RIPZ-12

Final Remedial Investigation Report Casmalia Resources Superfund Site Casmalia, California

E9-23

DRAWN	JOB NUMBER	CHECKED	CHCK'D DATE	APPROVED	APPRV'D DATE
CN	4088097619	WJF	1/11	WBC	1/11



Page 2 of 2